

**TAMPA FIRE RESCUE  
TRAINING  
176 S 34TH ST  
TAMPA, FL 33605**

**PFAS Sample Results**

- ★ >HAL
- ★ >1/2 HAL
- >1/4 HAL
- <1/4 HAL
- ▲ BDL
- ⊕ No Sample for this Analysis


**Wells PFAS Level**

- 0 >HAL
- 0 >1/2 HAL
- 0 >1/4 HAL
- 2 <1/4 HAL
- 4 Below Detection



Disclaimer  
This product is for reference purposes only and is not to be construed as a legal document. Any reliance on the information contained herein is at the user's own risk. The Florida Department of Health and its agents assume no responsibility for any use of the information contained herein or any loss resulting therefrom.

Source: Esri, DigitalGlobe, GeoEye, Earthstar Geographics, CNES/Airbus DS, USDA, USGS, AeroGRID, IGN, and the GIS User Community



Date: 7/25/2019