

COLLIER COUNTY WETLAND DETERMINATIONS

ACCESS = No way to access the site. Please cut an access path and resubmit the determination request.

Collier Co= Determination was done in our Collier Office

DITCH = Ditches on site

MAUP=Map shows uplands

MWET=Map shows wetlands

NDSP=Needs site plan to determine impacts

NTST = Not Staked. All four corners and impact areas should be staked.

Permit=Permit Issued for property

SPUP=Site Plan Upland

SPWE=Site Plan Wetland

UPLD=Upland

WTLD=Wetland

If your strap number is not listed, you may contact David Anthony or Anna Hall at Collier County at 239-252-2497 to request a determination. A fee is required. Contact them also for copies of determinations done before 2011.

Strap numbers beginning with 3765-3799

Folio#	Unit/Tract	Section	Determ	Date
37690320008	U022T006	S 150'	WTLD	12/26/07
37690520002	U022T008	S165'	UPLD	11/4/04
37690520109	U022T008	N165'	UPLD	11/4/04
37690640005	U022T010	E 1/2	UPLD	4/24/2009
37690640102	U022T010	W 1/2	UPLD	4/24/2009
37690720006	U022T012	S150'	NDSP	5/2/06
37690760008	U022T012	N180'	WTLD	4/6/06
37690800007	U022T013	N 1/2	WTLD	9/23/05
37690800104	U022T013	S 1/2	WTLD	9/23/05
37691000000	U22T155	S 180'	WTLD	7/29/2013
37691040002	no address		WTLD	11/3/2014
37691120003	U22T16S	N150'	WTLD	10/15/2013
37691280008	U022T017	S75'	WTLD	9/8/05
37691280008	U022T017	S75'	WTLD	9/20/05
37691280008	U022T017	S75'	WTLD	12/9/05
37691600002	U021T022	N180'	SPUP	5/7/02
37691720005	U022T022	S105'	WTLD	4/18/06
37692200003	U022T031	W165'	UPLD	3/15/05
37692480001	U022T035	S1/2	UPLD	1/14/06
37692640003	U022T037	S75' of N150'	WTLD	1/24/06
37692640003	Wilson Blvd		WTLD	9/17/2014
37692680005	U022T037	S180'	NDSP	3/28/07
37692800005	U022T039	N1/2	NDSP	8/27/04
37692801004	U022T039	S1/2	NDSP	8/27/04
37693000008	U022T041	S105'	UPLD	4/11/16
37693040000	U022T042	N180'	NDSP	2/9/07
37693080002	U022T042	S150'	NDSP	11/3/04
37693320005	U022T045	N1/2 OF S330'	WTLD	10/19/04
37693360007	U022T045	N1/2	WTLD	10/19/04
37693380003	U022T045	S1/2	WTLD	10/19/04

Folio#	Unit/Tract	Section	Determ	Date
37693400103	U022T046	N165'	NDSP	7/9/07
37693560001	U022T048	S75'	WTLD	12/4/06
37693660008	U022T049	S 1/2	NDSP	9/20/05
37693920007	U022T052	S75' OF N180'	NDSP	11/3/04
37694080001	U022T054	N180'	WTLD	10/12/05
37695400004	U022T072	N150'	WTLD	2/28/05
37695440006	U022T072	S180'	WTLD	3/27/06
37695640000	U022T074	S75' of N150'	MWET	10/18/05
37695960007	U022T080	N1/2 ONLY	WTLD	3/28/07
37695960104	U022T080	S1/2 ONLY	WTLD	3/28/07
37696960006	U022T096	N150'	UPLD	11/3/04
37697160009	U022T099	N180'	UPLD	11/3/04
37697280002	U022T101	N180'	UPLD	2/15/05
37697320002	U002T102	S180'	UPLD	4/11/05
37697760001	U22T108	4th St NE	UPLD	9/13/2013
37697760001	U22T16	S180'	UPLD	8/15/2013
37697760001	3105 4th Street NE		UPLD	6/21/2014
37698000003	U022T112	N 1/2	UPLD	4/11/05
37698120006	U022T114	S150'	UPLD	11/28/06
37698360002	U022T116	N180'	WTLD	12/26/06
37740040005	U023T001	N75'	UPLD	6/8/01
37740120006	U023T001	S180'	SPUP	12/23/02
37740160008	U023T002	N180'	WTLD	4/19/06
37740520004	U023T006	N180'	NDSP	11/12/03
37740840001	U023T009	S180'	WTLD	3/9/07
37740920002	U023T010	N75' OF S150'	WTLD	9/20/01
37741040004	U023T011	S105'	NDSP	5/7/03
37741120005	U023T011	N75' of S180'	NDSP	1/6/06
37741160007	U023T012	N180'	SPUP	6/27/07
37741560005	U023T018		NDSP	12/9/05
37741560005	U023T018		NDSP	12/9/05
37741640006	U023T019	W180'	WTLD	10/18/05
37741720007	U023T020	W180'	WTLD	4/12/06
37741960003	U023T023	E150'	UPLD	7/30/03
37742000001	U023T024	E150'	UPLD	2/4/04
37742040003	U023T024	W180'	UPLD	8/27/04
37742040003	U023T024	W180'	UPLD	9/2/04
37742200005		Jung Blvd	UPLD	7/29/09
37742640005	U023T032	E180'	UPLD	3/12/04
37742680007	U023T032	W150'	UPLD	4/11/16
37742760008	U023T033	E180'	UPLD	3/14/05
37742920000	U023T037	W180'	NDSP	4/30/07
37742960002	U023T037	E150'	UPLD	2/22/05
37743080004	U023T039	E150'	UPLD	7/18/01
37743200004	U023T040	E75' OF W180'	DITCH	1/3/06
37743280008	U023T041	E150'	DITCH	4/13/06
37743320007	U023T041	W180'	DITCH	10/3/06
37743480002	U023T043	N180'	UPLD	5/25/01
37743640004	U023T046	5ACRES	UPLD	3/12/03
37744440009	U023T061	W180'	UPLD	1/4/05
37744480001	U023T061	E150'	UPLD	10/7/04
37744520000	U023T062	5ACRES	UPLD	6/25/04

Folio#	Unit/Tract	Section	Determ	Date
37744640100	U023T064	W150'	WTLD	3/10/05
37744680005	U023T065	E180'	UPLD	1/20/06
37744720004	U023T065	W150'	UPLD	7/11/03
37744760006	U023T066	W75'	UPLD	10/17/05
37744880009	U023T067		UPLD	6/25/01
37745400006	U023T075	E150'	UPLD	11/4/04
37745480000	U023T076	W180'	WTLD	9/14/06
37745480000	U023T076	W180'	WTLD	9/14/06
37745480000	U023T076	W180'	WTLD	9/14/06
37745560001	U023T076	E75'	UPLD	4/8/03
37745640002	20th Avenue NE		UPLD	9/11/2015
37745680004	U023T078	E150'	UPLD	10/7/04
37745920007	U023T080	E75'	UPLD	1/24/06
37746040009	U023T081		UPLD	1/15/04
37746240003	U023T083	W150'	UPLD	7/7/06
37746560000	U023T087	W165'	UPLD	11/19/03
37746600009	U023T087	E165'	NDSP	9/11/01
37746960008	U023T092	E75' of W180'	UPLD	3/24/06
37747040008	U023T092	E150'	UPLD	9/19/01
37747080000	U023T093	W165'	UPLD	9/29/06
37747240002	U023T094	E75' OF W180'	UPLD	6/25/04
37747400004	U023T096	E150'	UPLD	9/14/06
37747440006	U023T096	W180'	UPLD	11/4/04
37747560009	U023T098	W180'	DITCH	4/6/07
37747640000	U023T099	E180'	NDSP	3/24/06
37747920005	U023T102	W150'	UPLD	10/22/01
37748160000	U023T103	W75' of E180'	UPLD	9/8/05
37748240001	U023T104	E180'	UPLD	7/11/07
37748320002	U023T105	E180'	MAUP	10/13/05
37748760002	U023T110	E150'	UPLD	1/31/03
37748800001	U023T111	E150'	UPLD	1/28/05
37748800001	U023T111	E180'	UPLD	1/29/05
37748840003	U023T111	W180'	UPLD	11/27/01
37749240000	U023T116	E150'	UPLD	3/9/05
37749280002	U023T117	E180'	NDSP	1/19/05
37749280002	U023T117	E180'	SPUP	6/21/05
37749360003	U023T118	W150'	MAUP	1/15/04
37749520005	U023T119	E75' OF W150'	MAUP	5/15/03
37749840002	T023U122	W165'	UPLD	10/20/06
37749960005	U023T124	E150'	SPUP	10/28/03
37750240002	U023T128	N75' OF S150'	SPUP	6/30/03
37750280004	U023T129	E 1/2	NDSP	11/1/05
37750280101	U023T129	W 1/2	UPLD	11/1/05
37750320003	U023T130	S150'	WTLD	9/22/04
37750320003	U023T130	S150'	SPUP	6/26/05
37750360005	U023T130	N180'	NDSP	10/8/04
37750640000	U023T134	N180'	WTLD	1/30/07
37750840004	U023T137		UPLD	10/17/05
37751240001	U023T142	N180'	WTLD	3/9/05
37751240001	U023T142	N180'	NDSP	10/14/05
37779240007	U062T074	W75'	UPLD	12/13/04
37800160003	U024T003	S180'	UPLD	9/3/03

Folio#	Unit/Tract	Section	Determ	Date
37800200002	U024T003	N75'	UPLD	6/6/02
37800280006	U024T004	S150'	NDSP	3/23/07
37800320005	U024T004	S75'	SPUP	3/26/03
37800400006	U024T006	N180'	NDSP	11/18/02
37800400006	U024T006	N180'	SPUP	4/19/05
37800640002	U024T008	S75' OF N180'	NDSP	2/22/02
37800720003	U024T009	N150'	UPLD	4/6/05
37800760005	U024T011	W350'	UPLD	10/17/05
37800760102	U024T011	E350'	UPLD	10/17/05
37800920007	U024T012	N75' OF S150'	WTLD	5/16/01
37800960009	U024T012	N180'	NDSP	8/30/04
37801320004	U024T016	S165'	UPLD	2/3/05
37801320101	U024T016	N165'	UPLD	2/3/05
37801440007	U024T018	E180'	UPLD	9/23/05
37801560000	U024T019	E75' OF W180'	NDSP	2/14/07
37801680003	U24T21	E 150'	UPLD	7/22/2013
37801760004	U024T022	E150'	UPLD	9/29/06
37801880007	U024T023	E 150'	UPLD	5/5/10
37802000006	U024T024	W105'	WTLD	11/12/03
37802040008	U024T025	W180'	UPLD	8/27/03
37802320003	U024T028	W150'	UPLD	2/6/03
37802520007	U024T030	W150'	UPLD	10/17/01
37802840004	U024T034	E180'	UPLD	3/24/06
37803000005	U024T036	W75' OF E180'	NDSP	12/6/04
37803000005	U024T036	W75' of E180'	SPUP	5/2/05
37803200009	U024T038	E75' OF W180'	WTLD	7/18/06
37803240001	U024T038	E150'	WTLD	1/31/05
37803360004	U024T039	E75'	UPLD	12/9/03
37803400003	U024T040	W75' OF E150'	UPLD	10/2/01
37803480007	U024T040	E75'	UPLD	8/20/01
37803560008	U024T041	E105'	UPLD	2/20/02
37803720000	U024T043		UPLD	9/3/03
37803800001	U024T044	E150'	UPLD	1/19/05
37803840003	1010 18th Ave NE		UPLD	2/14/14-Collier Co
37803880005	U024T046	W75' OF E180'	SPUP	3/12/03
37803920004	U024T046	W75'	SPUP	7/9/01
37804080008	U024T047	W75'	UPLD	7/30/03
37804120007	U024T047	W150'	UPLD	8/3/01
37804360003	U024T049	E180'	NDSP	1/6/06
37804600006	U024T052	W150'	SPUP	3/6/02
37804640008	U024T052	W75' OF E180'	SPUP	3/6/02
37804760001	U024T054	W165'	MWET	4/6/06
37804760108	U014T054	E165'	DITCH	4/7/06
37805280001	U024T060	W180'	UPLD	1/6/06
37805600005	U024T065	E180'	UPLD	7/18/06
37805640007	U024T065	W150'	UPLD	9/29/06
37805640007	U024T065	W150'	UPLD	10/9/06
37805720008	U024T066	W150'	UPLD	9/29/04
37805760000	U024T067	E180'	UPLD	2/12/03
37806080006	U024T070	W150'	DITCH	2/23/07
37806240008	U024T071	W75' OF E180'	UPLD	4/13/04
37806440002	U024T074	E150'	UPLD	12/5/02

Folio#	Unit/Tract	Section	Determ	Date
37806640006	U024T077	W75'E150'	UPLD	8/10/07
37806880002	U024T079	E105'	WTLD	4/19/06
37806920001	U024T079	W180'	WTLD	9/8/05
37807080005	U024T081	E150'	UPLD	3/4/03
37807360000	U024T087	N 1/2	UPLD	2/18/05
37807400009	U024T087	S 1/2	UPLD	2/18/05
37807440001	U024T088	S 1/2	UPLD	2/18/05
37807441000	U024T088	N 1/2	UPLD	2/18/05
37807720006	U024T094	E150'	MAUP	10/28/03
37807920000	U024T098	5ACRES	UPLD	12/13/04
37807960002	U024T099	S1/2	NDSP	10/22/04
37807960002	U024T099	S 1/2	SPUP	6/15/05
37807960109	U024T099	N1/2	MAUP	6/10/02
37808000107	U024T100	5 ACRES	SPUP	11/25/02
37808120003	U024T102	E180'	UPLD	12/13/07
37808720005	U024T110	W180'	UPLD	2/15/06
37808840008	U024T111	W180'	UPLD	3/26/02
37808960001	U024T112	W75'	UPLD	3/26/03
37809200003	U024T115	W180'	UPLD	7/10/03
37809360008	U024T117	S330'	WTLD	4/12/06
37809640003	U024T120	W75'	WTLD	10/22/04
37809680005	U024T121	E165'	UPLD	1/3/03
37809720004	U024T122	E75' OF W150'	UPLD	8/29/01
37809920008	U024T124	W150'	MAUP	8/1/02
37810160006	U024T127	W180'	MAUP	2/3/03
37810280009	U024T129	S150'	UPLD	12/28/04
37810520002	U024T132	N150'	UPLD	7/11/03
37810800007	U024T134	N150'	UPLD	12/14/06
37810840009	U024T135	S150'	UPLD	4/26/06
37811320007	U024T141	S75' of N180'	UPLD	11/1/05
37860040008	U025T001	S75' OF N150'	UPLD	7/18/06
37860240002	U025T002	N75' of S150'	UPLD	11/1/05
37860280101	U025T003	E 1/2	UPLD	3/31/06
37860320003	U025T004	S165'	UPLD	5/14/02
37860340009	U025T004	N165'	UPLD	1/6/06
37860440006	U025T006	N180'	UPLD	11/4/02
37860520007	U025T006	S150'	UPLD	11/15/06
37860560009	U025T007	W75'	UPLD	8/3/01
37860600008	U025T007	S180'	UPLD	1/6/06
37860840004	U025T011	S105'	UPLD	3/10/05
37860920005	U025T011	N75' OF S180'	UPLD	6/2/06
37861360004	U025T016	S75'	UPLD	1/24/06
37861440005	U025T018	W150'	UPLD	4/11/07
37861760002	U025T022	W75' OF E150'	UPLD	7/21/03
37861880005	U025T023	W180'	UPLD	12/28/04
37861960006	U025T024	E150'	UPLD	3/24/06
37862040006	U025T025	E75'	UPLD	3/3/03
37862400002	U025T027	W105'	SPUP	4/7/04
37862720009	U025T030	W75'	UPLD	5/5/04
37863000003	U025T032	E180'	UPLD	2/17/05
37863240009	U025T035	E180'	UPLD	10/18/05
37863520004	U025T038	W105'	UPLD	11/23/04

Folio#	Unit/Tract	Section	Determ	Date
37863640007	U025T039	W180'	UPLD	10/13/03
37863960004	U025T043	E75'	UPLD	11/1/04
37864200006	U025T045	E150'	UPLD	1/6/06
37864240008	U025T045	W180'	UPLD	11/10/03
37864480004	U025T048	W75'	UPLD	8/24/07
37864600004	U025T049	E75' OF W150'	NDSP	4/28/03
37864640006	U025T049	E180'	WTLD	4/25/06
37864680008	U025T050	W75'	UPLD	11/6/01
37864760009	U025T050	E75' OF W150'	NDSP	9/8/01
37864840000	U025T052	W75'	UPLD	5/30/03
37864880002	U025T025	E75' OF W180'	UPLD	2/26/03
37865000001	24th Ave NE		UPLD	10/13/2014
37865200005	U025T055	W165'	UPLD	1/10/02
37865200005	U025T055	E 1/2	MAUP	3/7/06
37865240007	U025T056	E75' of W180'	NDSP	3/31/06
37865320008	U025T056	N 1/2	UPLD	5/3/05
37865400009	U025T057	E75'	UPLD	10/8/02
37865440001	U025T057	W75' OF E150'	WTLD	2/12/04
37865560004	U025T029	E180'	UPLD	6/29/01
37865560004	U025T058	E150'	UPLD	6/29/01
37865640005	U025T059	W180'	SPUP	1/7/02
37865760008	U025T060	W180'	NDSP	5/15/07
37865880001	20th Ave NE		UPLD	2/3/2016
37866120100	U025T065	E 1/2	NDSP	9/23/05
37866120100	U025T065	E165'	SPUP	1/24/06
37866160005	U025T066	W75'	UPLD	1/15/04
37866280008	U025T066	W75' OF E180'	UPLD	9/22/04
37866280008	U025T066	W75' OF E180'	UPLD	9/22/04
37866320007	U025T067	W150'	UPLD	6/30/04
37866440000	U025T068	E180'	UPLD	5/5/04
37866480002	U025T068	E75' of W150'	UPLD	7/22/05
37866600002	U025T069	E75' OF W180'	UPLD	8/30/04
37866720005	U025T070	E75' OF W150'	UPLD	5/19/04
37866920009	U025T072	5ACRES	UPLD	6/11/01
37866960001	U025T073	E165'	UPLD	3/26/02
37867000009	U025T073	W165'	UPLD	3/26/02
37867080003	U025T074	W180'	UPLD	3/18/05
37867480001	U025T078	E75'	UPLD	7/26/04
37867600001	U025T079	W180'	NDSP	4/21/04
37867680005	U025T080	W105'	UPLD	4/12/04
37867840007	U025T082		UPLD	12/9/05
37867840104	U025T082		UPLD	12/9/05
37867960000	U025T083	E105'	UPLD	6/15/03
37868120001	U025T084	W75' OF E180'	UPLD	11/19/03
37868160003	U025T085	E180'	NDSP	9/23/05
37868320005	U025T086	E75' OF W150'	UPLD	2/12/07
37868360007	U025T086	E180'	UPLD	9/12/06
37868360007	U025T086	E180'	UPLD	9/12/06
37868720003	U025T090	5ACRES	UPLD	3/26/02
37868880008	U025T092	W75' OF E150'	MAUP	2/13/03
37869760004	U025T101	E180'	UPLD	10/17/05
37869760004	U025T101	E180'	UPLD	10/17/07

Folio#	Unit/Tract	Section	Determ	Date
37870120002	U025T106	W150'	UPLD	12/6/04
37870360008	U025T108	W150'	UPLD	12/13/04
37870360008	U025T108	W150'	UPLD	12/13/04
37870480001	U025T110	E250'	UPLD	3/26/02
37870600001	U025T113	5ACRES	UPLD	8/23/04
37870760006	U25T116	W150'	UPLD	8/8/2014
37895880103	U022T078	N165'	NDSP	11/1/05
37920480003	U026T007	W180'	NDSP	7/29/02
37921400008	U026T015	E180'	UPLD	2/20/07
37921840008	U026T019	E180'	UPLD	12/26/01
37923720003	U026T038	W180'	UPLD	9/21/04
37923720003	U026T038	W180'	UPLD	9/24/04
37923840006	U026T039	E75' OF W150'	UPLD	10/28/03
37923960009	U026T041	S1/2	UPLD	11/18/04
37924440007	U026T046	W165'	UPLD	4/1/02
37924480009	U026T046	E165'	UPLD	6/5/07
37925600008	U026T057	W75' of E180'	NDSP	3/16/06
37926760002	U026T072	W180'	UPLD	10/8/02
37926880005	U026T073	E75'	UPLD	10/11/05
37927080008	U026T075	W150'	WTLD	8/16/06
37927320001	U026T078	W180'	NDSP	1/6/06
37927560007	U026T080	E180'	UPLD	6/23/05
37927600006	U026T081	E165'	UPLD	10/9/03
37927640105	U026T082	4240 Pine Ridge R	UPLD	3/7/08
37928080007	U026T087	E75'	WTLD	5/21/04
37928960004	U026T096	W45' of E 150'	UPLD	9/5/07
37929400000	U026T100	W180'	NDSP	8/12/02
37930160009	U026T106	E75' OF W150'	UPLD	3/25/04
37930200008	U026T107	E75' of W150'	UPLD	10/11/05
37930200008		Pine Ridge Road	UPLD	1/10/2014
37930320001	U026T108	W150'	SPUP	7/19/07
37930840002	U026T115	S150'	UPLD	11/25/02
37931400001	U026T126	W105'	UPLD	7/3/01
37980040001	U027T001	W150'	UPLD	8/26/03
37980240005	U027T004	S1/2	UPLD	6/22/06
37980240102	U027T004	N 1/2	WTLD	4/26/06
37980920008	U027T014	W180'	UPLD	1/23/03
37980960000	U027T015	E150'	UPLD	9/14/05
37981040000	U027T016	W1/2	UPLD	8/7/03
37981160003	U027T017	W150'	MAUP	8/28/01
37981280006	U027T019	E180'	NDSP	3/31/06
37981400006	U027T020	W165'	SPUP	9/26/02
37982000007	U027T026	W75'	UPLD	7/9/07
37982120000	U027T027	E105'	UPLD	1/2/06
37982400005	U027T030	E75' OF W180'	UPLD	5/3/04
37982520008	U027T030	W75' of E150'	NDSP	7/9/07
37982560000	U027T031	E75'	UPLD	12/13/06
37982680100	U027T032	E150'	UPLD	1/22/02
37982800003	13th Ave SW		UPLD	2/27/2015
37983401003	U027T041	N300'	UPLD	8/31/05
37984600007	U027T053	W105'	SPUP	3/18/03
37985160009	U027T059	W105'	NDSP	4/13/05

Folio#	Unit/Tract	Section	Determ	Date
37985160009	U027T059	W105'	SPUP	5/2/06
37985640008	U027T063	E165'	NDSP	10/10/01
37986120006	U027T069	W1/2	NDSP	10/18/04
37986120006	U027T069	W 1/2	SPUP	3/25/05
37988560004	U027T092	E75' OF W150'	SPUP	6/5/02
37988840009	U027T095	W180'	NDSP	8/6/07
37989000000	U027T096	W180'	UPLD	2/20/03
37989320007			UPLD	2/25/2011
37990160007	U027T107	E75' of W150'	UPLD	2/8/05
37990240008	U027T107	E105'	SPUP	4/8/02
37990360001	U27T108	E180'	WTLD	3/7/2014
37991120004	U027T115	5ACRES	MAUP	12/10/03
37991680007	U027T120	E150'	UPLD	1/4/02
37992800006	U027T131	W150'	UPLD	1/15/04
37993800005	U027T139	W180'	NDSP	9/13/05
37993920008	U027T140	E75'	UPLD	10/15/01
37994320005	U027T144	W180'	UPLD	1/22/02
37994360004	U027T144	W75' OF E150'	UPLD	3/26/02
37994480000	U027T145	W75'	SPUP	5/30/03
37994880008	U027T149	N180'	UPLD	5/26/04
37994960009	U027T150	W 1/2	NDSP	11/8/05
37994960009	U027T150	E 1/2	WTLD	11/8/05
37995280005	U027T154	E 1/2	NDSP	9/25/05
37995960008	U027T164	N150'	UPLD	2/20/04
37996240002	U027T016	S180'	UPLD	11/18/04
37996520007	U027T173	E150'	UPLD	10/14/13-Collier Co
37997200009	U027T179	W75' OF E150'	UPLD	6/30/06
37997800001	U027T185	N165'	MAUP	11/20/02
37997960006	U027T188	5 ACRES	UPLD	8/28/01