

COLLIER COUNTY WETLAND DETERMINATIONS

ACCESS = No way to access the site. Please cut an access path and resubmit the determination request.

Collier Co= Determination was done in our Collier Office

DITCH = Ditches on site

MAUP=Map shows uplands

MWET=Map shows wetlands

NDSP=Needs site plan to determine impacts

NTST = Not Staked. All four corners and impact areas should be staked.

Permit=Permit Issued for property

SPUP=Site Plan Upland

SPWE=Site Plan Wetland

UPLD=Upland

WTLD=Wetland

If your strap number is not listed, you may contact David Anthony or Anna Hall at Collier County at 239-252-2497 to request a determination. A fee is required. Contact them also for copies of determinations done before 2011.

Strap numbers beginning with 3956-3979

Folio#	Unit/Tract	Section	Determ	Date
03959396000	U059T040	E105'	UPLD	12/26/07
3977492005		3320 41st Ave NE	UPLD	9/13/13
39590080006	U059T002	S150'	NDSP	9/23/05
39590120005	U059T002	N180'	UPLD	12/3/03
39590280000	U59T4	S150"	WTLD	12/2/2013
39590280000	U59T4	S 150'	WTLD	12/2/2013
39590480004	U059T007	S180'	WTLD	7/16/02
39590560005	U059T008	S150'	DTCH	12/26/07
39590720007	U059T010	S150'	UPLD	5/22/01
39590840000	U059T012	S150'	UPLD	4/14/03
39590880002	39	N180'	UPLD	2/20/04
39590960003	U059T013	S180'	UPLD	6/30/03
39591040003	U059T014	S180'	UPLD	5/2/03
39591120004	U059T015	N1/2	DITCH	1/17/07
39591320008	U059T018	S105'	UPLD	12/22/03
39591360000	U059T018	N75' OF S180'	UPLD	10/6/03
39591480003	U059T019	W75' OF E150'	UPLD	7/21/03
39591520002	U059T019	W105' OF W180'	UPLD	11/15/04
39591560004	U052T020	E75' of W150'	DITCH	10/14/05
39591720006	U059T021	E150'	UPLD	11/21/01
39591800007	U059T022	W75' OF E180'	UPLD	5/2/03
39592080004	U059T024	S75' of N150'	DITCH	10/4/05
39592160005	U059T025	N180'	NDSP	11/17/04
39592200004	U059T025	S150'	NDSP	11/17/04
39592280008	U059T026	S75' of N150'	DITCH	11/17/05
39592280008	U059T026	S75' OF N150'	WTLD	11/17/04
39592320007	U059T026	S105'	UPLD	6/11/01
39592360009	U059T026	N75'	NDSP	11/17/04
39592720005	U059T029	N105'	UPLD	5/28/03
39592800006	U059T030	N205'	SPUP	8/16/01

Folio#	Unit/Tract	Section	Determ	Date
39592820002	U059T030	S205'	SPUP	12/2/03
39592820002	U059T030	S205'	SPUP	5/25/05
39592840008	U059T031	6 ACRES	UPLD	5/6/03
39593040001	U059T033	N150'	DITCH	5/21/06
39593080003	U059T033	N75' OF S180'	UPLD	11/6/01
39593160004	U059T034	S75'	UPLD	6/5/01
39593240005	U059T034	N75' OF S150'	MAUP	10/24/02
39593440009	U059T036	S75'	UPLD	10/15/02
39593560002	U059T037	S75' of N150'	DITCH	4/18/06
39593960000	U059T040	E105'	UPLD	12/26/07
39594000008	U059T040	W75'	UPLD	3/24/08
39594040000	U059T040	W150'	UPLD	6/21/04
39594120001	U059T041	E150'	UPLD	4/21/03
39594280006	U059T043	N75' OF S180'	SPUP	7/27/04
39594400006	U059T044	S75' OF N180'	SPUP	6/25/04
39594440008	U059T044	N105'	DITCH	1/3/06
39594720003	U059T047	N150'	UPLD	5/23/02
39594880008	U059T048	S75' OF N150'	UPLD	11/19/03
39594960009	U059T049	W105'	DITCH	11/10/03
39594960009	U059T049	W105'	NDSP	11/19/03
39595120000	U059T050	E74' W1250'	DITCH	12/4/06
39595400005	U059T052	W75' OF E180'	UPLD	5/2/03
39595440007	U059T053	S75' OF N180'	DITCH	11/2/05
39595560000	U059T054	S180'	UPLD	3/3/03
39595680003	U059T055	N105'	MAUP	6/12/03
39595760004	U059T055	N75' OF S150'	UPLD	6/28/04
39596000006	U059T057	S75' OF N180'	UPLD	4/21/03
39596240002	U059T058		NDSP	2/1/05
39596280004	U059T059	S150'	MAUP	11/7/02
39596320003	U059T059	S75'	NDSP	1/3/06
39596360005	U059T059	S75' OF N180'	MAUP	6/12/03
39596720001	U059T064	N180'	WTLD	6/25/01
39596800002	U059T064	S75'	UPLD	2/14/02
39596880006	U059T065	S180'	WTLD	5/13/04
39597080009	U059T067	S75' OF N150'	WTLD	5/12/04
39597400003	U059T070	E105'	UPLD	12/9/05
39597480007	U059T070	E75' OF W150'	UPLD	3/12/03
39597520006	U059T070	W75' OF E180'	UPLD	3/12/03
39597600007	U059T071	E75' of W180'	UPLD	6/16/05
39597680001	U059T071	W75' OF E150'	UPLD	8/20/03
39597760002	U059T072	W150'	UPLD	11/19/01
39597840003	U059T073	N150'	UPLD	11/1/04
39598040006	U059T074	N105'	DITCH	5/3/06
39598160009	U059T077	S150'	UPLD	11/19/03
39598200008	U059T077	S75' OF N180'	UPLD	11/19/01
39598240000	U059T077	N105'	UPLD	1/13/06
39598280002	U059T078	S105'	SPUP	11/19/01
39598400002	U059T078	N75' OF S180'	WTLD	3/31/04
39598440004	U059T079	W75' of E150'	NDSP	1/13/06
39598640008	U059T080	E75' OF W180'	WTLD	3/11/03
39598680000	U059T080	W75' OF E150'	SPUP	9/18/01
39598920003	U059T083	N180'	SPUP	6/23/05

Folio#	Unit/Tract	Section	Determ	Date
39599320000	U059T086	N75'	MAUP	1/9/03
39599520004	U059T088	N75'	UPLD	8/3/01
39599720105	U059T090	5ACRES	UPLD	4/8/04
39599760000	U059T091	N75'	UPLD	8/29/01
39599800009	U059T092	N105'	NDSP	7/12/01
39599840001	U059T092		UPLD	12/15/03
39599920002	U059T092	S75' of N180'	SPUP	11/8/05
39600000002	U059T093	N75' OF S180'	UPLD	8/12/04
39600040004	U059T093	N75'	UPLD	11/21/02
39600080006	U059T093	S105'	SPUP	5/30/01
39600280000	U059T095	N75' OF S180'	MAUP	1/9/03
39600320009	U059T095	S105'	UPLD	2/13/03
39600400000	U059T096	N105'	UPLD	7/22/03
39600840000	U059T100	E105'	UPLD	10/28/03
39600880002	U059T100	W75' OF E180'	WTLD	9/9/04
39601000001	U059T101	E75' OF W180'	UPLD	2/28/07
39601080005	U059T102	E105'	NDSP	6/16/05
39601080005	U059T102	E105'	SPUP	10/12/06
39601280009	U059T103	S105'	UPLD	6/16/05
39601320008	U059T104	S75' OF N180'	UPLD	5/2/03
39601400009	U058T104	N105'	DITCH	4/18/06
39601480003	U059T106	5ACRES	MAUP	6/12/03
39601560004	U059T107	N180'	UPLD	3/14/06
39601600003	U059T107	N75' OF S150'	UPLD	11/4/02
39601720006	U059T109	W180'	UPLD	8/12/04
39601880001	U059T110	W75'	MAUP	6/12/03
39601920000	U059T111	E150'	UPLD	1/13/06
39602000000	U059T111	E75' OF W180'	MWET	12/30/04
39602040109	U059T112	W 1/2	WTLD	6/4/07
39602240006	U059T114	S180'	UPLD	1/28/03
39602440000	U059T116	N75' OF S180'	MAUP	2/19/03
39602560003	U059T117	N75' OF S150'	UPLD	7/21/03
39602640004	U059T118	S75' OF N150'	MAUP	3/4/03
39602840008	U059T119	S75' of N180'	UPLD	6/16/05
39650040009	U060T001	S165'	MAUP	11/19/03
39650200001	U060T003	S75' of N150'	WTLD	9/23/05
39650240003	U060T003	N75'	UPLD	10/15/05
39650280005	U060T004	S75'	MAUP	6/12/03
39650320004	U060T004	N75' OF S150'	UPLD	1/10/02
39650360006	U060T004	N180'	MAUP	11/7/02
39650440007	U060T005	N150'	UPLD	2/26/06
39650440007	U060T005	N150'	WTLD	12/26/01
39650520008	U060T006	N75' OF S150'	UPLD	11/15/06
39650560000	U060T006	N180'	UPLD	1/13/03
39650760004	U060T008	N75' OF S150'	SPUP	8/5/02
39650880007	U060T008	N105'	NDSP	3/17/06
39650880007	U060T008	N105'	SPUP	5/10/07
39650960008	U060T009	W180'	UPLD	12/15/03
39651080000	U060T010	E105'	UPLD	5/12/04
39651200000	U060T011	W180'	UPLD	11/22/04
39651600008		16th Street NE	UPLD	12/3/2012
39651640000		16th Street NE	UPLD	12/3/2012

Folio#	Unit/Tract	Section	Determ	Date
39651720001	U060T018	S180'	MAUP	10/4/05
39651760003	U060T018	N150'	UPLD	4/21/03
39651920005	U060T020	E180'	UPLD	3/31/03
39652040007	U060T021	E150'	UPLD	10/29/01
39652240001	U060T023	S150'	UPLD	4/21/03
39652280003	U060T023	N180'	UPLD	3/14/02
39652680001	U060T026	N75 of S180	UPLD	9/23/2014
39652800001	U060T028	N150'	NDSP	6/16/05
39652880005	U060T029	N75' OF S150'	UPLD	2/27/07
39653000004	U060T029	S75' OF N150'	WTLD	12/30/04
39653080008	U060T031	W150'	NDSP	3/28/07
39653080008	U060T031	W150'	SPUP	5/17/07
39653200008	U060T032	N75' OF S150'	NDSP	10/21/04
39653200008	U060T032	N75' of S150'	SPUP	9/5/05
39653400002	U060T033	S75' OF N150'	UPLD	7/21/03
39653440004	U060T034	S75'	NDSP	10/10/06
39653480006	U060T034	N75' OF S150'	NDSP	2/1/05
39653480006	U060T034	N75' of S150'	SPUP	2/22/05
39653550004	U060T034	S75'	WTLD	10/12/06
39653550004	U060T034	S75	WTLD	10/12/06
39653640008	U060T036	S75' OF N180'	UPLD	1/23/03
39653680000	U060T036	N75' OF S150'	UPLD	5/5/04
39653760001	U060T036	N105'	UPLD	3/14/06
39654120006	U060T040	W150'	UPLD	5/3/01
39654160008	U060T040	W75' OF E180'	UPLD	6/28/04
39654240009	U060T041	E75' OF W180'	UPLD	3/26/04
39654280001	U060T041	E75'	UPLD	6/12/03
39654480005	U060T043	S75' of N150'	UPLD	4/14/05
39654520004	U060T043	N75'	UPLD	5/12/04
39654560006	U060T043	S180'	UPLD	4/14/05
39654680009	U060T044	S75' OF N150'	UPLD	8/20/03
39654880003	U060T047	S75'	UPLD	6/12/06
39655000002	U060T048	S105'	UPLD	4/14/05
39655040004	U060T048	N75'	UPLD	7/21/03
39655200006	U060T049	E75'	MAUP	6/12/03
39655280000	U060T050	W75' OF E180'	UPLD	10/8/02
39655320009	U060T050	W150'	UPLD	10/2/03
39655520003	U060T053	N75' OF S150'	MAUP	6/12/03
39655560005	U060T053	N180'	UPLD	6/28/04
39656040003	U060T056	N75'	UPLD	1/13/06
39656280009	U060T059	S150'	DITCH	9/18/05
39656320008	U060T059	N180'	UPLD	9/19/01
39656400009	U060T061	6ACRES	UPLD	3/12/04
39656440001	U060T062	S150'	UPLD	5/14/02
39656480003	U060T062	S75' OF N180'	MAUP	12/10/03
39656560004	U060T063	S105'	UPLD	10/28/03
39656600003	U060T063	N150'	UPLD	5/23/02
39656920000	U060T066	N75' OF S150'	UPLD	6/11/01
39656960002	U060T066	S75'	UPLD	8/3/01
39657000000	U060T066	S75' of N180'	UPLD	1/24/06
39657080004	U060T067	N75'	MAUP	6/12/03
39657160005	U060T068	N75' OF S150'	UPLD	4/8/03

Folio#	Unit/Tract	Section	Determ	Date
39657240006	U060T068	S75' OF N180'	UPLD	4/8/03
39657400008	U060T069	E75'	UPLD	1/13/06
39657440000	U060T070	W75' of E180'	UPLD	11/9/05
39657680006	U060T072	E105'	UPLD	9/8/05
39657760007	U060T072	W75' OF E180'	UPLD	3/26/03
39657800006	U060T073	S105'	UPLD	10/2/01
39658120002	U060T076		UPLD	4/1/02
39658120109	U060T076	S150'	UPLD	4/23/02
39658320006	U060T078	S105'	MAUP	2/20/03
39658360008	U060T078	N75' of S180'	UPLD	10/4/05
39658440009	U060T079	W105'	MAUP	10/24/02
39658520000	U060T079	W75' OF E150'	DITCH	12/30/05
39658520000	U060T079	W75' OF E150'	WTLD	12/30/04
39658600001	U060T080	W75'	UPLD	8/22/01
39658640003	U060T080	E105'	UPLD	6/11/01
39658680005		47th Ave NE	UPLD	11/26/2012
39658760006	U060T082	E75' OF W150'	UPLD	6/22/06
39658840007	U060T082	W75'	UPLD	6/11/01
39658960000	U060T083	N105'	UPLD	9/5/05
39659040000	U060T083	N75' OF S150'	UPLD	4/8/03
39659080002	U060T084	S180'	UPLD	5/12/04
39659120001	U060T084	S75' OF N150'	UPLD	4/21/03
39659280006	U060T085	N105'	UPLD	9/3/03
39659320005	U060T086	N75'	UPLD	8/3/01
39659360007	U060T086	S75' OF N150'	UPLD	8/3/01
39659520009	U060T087	N180'	DITCH	2/2/06
39659560001	U060T088	S180'	UPLD	4/21/04
39659600000	U060T088	S75' OF N150'	MAUP	6/12/03
39659640002	U060T088	N75'	UPLD	9/3/03
39659720003	U060T089	N105'	NDSP	11/22/04
39659720003	U060T089	N105'	SPUP	5/10/05
39659840006	U060T091	5ACRES	UPLD	6/21/04
39659960009	U060T092	N105'	UPLD	4/14/05
39660120003	U060T094	S75'	MAUP	6/12/03
39660160005	U060T094	N75' of S150'	UPLD	6/16/05
39660240006	U060T095	S105'	WTLD	2/1/05
39660720005	U060T098	S75' OF N180'	UPLD	3/14/02
39660840008	U060T099	E150'	UPLD	8/16/01
39660880000	U060T099	w180	DITCH	12/15/05
39660920009	U060T100	E180'	UPLD	3/25/04
39661000009	U060T100	E75' OF W150'	UPLD	12/19/03
39661200003	U060T102	W75' OF E180'	UPLD	12/21/04
39661240005	U060T102	W75'	MAUP	12/13/02
39661280007	U060T102	E75' OF W150'	UPLD	12/21/04
39661440009	U060T104	N180'	UPLD	12/14/06
39661800005	U060T111	5ACRES	UPLD	7/21/03
39661840007	U060T112	N 1/2	UPLD	6/27/05
39661840104	U060T112	S 1/2	DITCH	6/27/05
39661880009	U060T113	5 ACRES	UPLD	5/5/04
39661960000	U060T115	S1/2	DITCH	8/7/07
39662160003	U060T120	6 ACRES	UPLD	12/11/02
39710040004	U061T001		MAUP	12/19/02

Folio#	Unit/Tract	Section	Determ	Date
39710360001	U061T007	S75' OF N180'	UPLD	5/19/04
39710400000	U061T008	S105'	UPLD	12/28/04
39710520003	U061T008	N75' OF S180'	UPLD	9/4/01
39710600004	U061T009	S75' of N180'	UPLD	9/23/05
39710640006	U061T009	S75'	UPLD	9/8/04
39710720007	U061T010	N75' OF W180'	UPLD	9/27/04
39710760009	U061T010	S105'	UPLD	6/6/02
39710840000	U061T011	S150'	WTLD	10/11/05
39710880002	U061T011	S75' OF N180'	WTLD	12/18/06
39710920001	U061T011	N105'	WTLD	1/12/05
39710960003	U061T012	N75'	WTLD	10/12/05
39711000001	U061T012	S75' OF N150'	MWET	12/7/04
39711160006	U061T014	S75' OF N150'	UPLD	10/4/04
39711200005	U061T014	N75' OF S180'	DITCH	4/7/06
39711240007	U061T014	N75'	SPUP	4/21/04
39711360000	U061T015	S75' of N180'	UPLD	8/22/05
39711440001	U061T015	N105'	UPLD	10/28/03
39711600003	U061T017	S75' OF N180'	UPLD	4/14/02
39711680007	U061T017	N105'	UPLD	11/9/05
39711760008	U061T018	N75' OF S150'	UPLD	10/15/01
39712120003	U061T022	E150'	WTLD	4/29/05
39712160005	U061T022	E75' OF W180'	WTLD	9/27/04
39712200004	45th Ave NE		WTLD	4/18/2016
39712520001	U061T025	W75' OF E150'	UPLD	6/2/03
39712760007	U061T027	W75'	NDSP	10/7/05
39712800006	U061T027	E75' of W150'	NDSP	10/7/05
39712880000	U061T028	W75' OF E180'	WTLD	3/31/04
39713080003	U061T029	W75' OF E180'	NDSP	4/21/04
39713120002	U061T030	E105' OF E180'	SPUP	5/10/01
39713160004	U061T030	W75' OF E18	SPUP	3/3/03
39713240005	U061T030	W75'	UPLD	2/4/04
39713360008	U061T032	E150'	UPLD	5/2/03
39713480001	U061T033	W105'	DITCH	9/25/05
39713520000	U061T033	E75'	UPLD	12/23/02
39713560002	U061T033	W75' OF E150'	UPLD	3/5/04
39713760006	U061T035	W105'	DITCH	10/25/06
39713920008	U061T036	W180'	NDSP	7/19/05
39713920008	U061T036	E75' of W180'	SPUP	11/16/05
39714080002	U061T037	E75'	WTLD	3/25/04
39714120001	U061T037	W105'	NDSP	12/13/04
39714200002	U061T038	E150'	SPUP	1/31/05
39714200004	U061T038	W75' OF E150'	WTLD	11/26/03
39714280006	U061T038	W75'	WTLD	8/17/04
39714360007	U061T039	W75' OF E180'	UPLD	6/7/04
39714480000	U061T040	W75'	UPLD	6/7/04
39714520009	U061T040	E75' of W150'	MAUP	10/2/05
39714640002	U61T41	E180'	UPLD	1/21/2014
39714680004	U061T042	W75'	NDSP	1/22/04
39714720003	U061T042	W75' OF E180'	DITCH	12/15/05
39714800004	U061T042	E75' of W150'	DITCH	2/2/06
39715080001	U061T045	E75'	UPLD	5/24/04
39715120000	U061T045	E75' OF 180'	WTLD	1/4/05

Folio#	Unit/Tract	Section	Determ	Date
39715200001	U061T046	W75' OF E150'	WTLD	7/9/03
39715280005	U061T046	E75' OF W180'	WTLD	10/12/06
39715400005	U061T047	W75' of E150'	UPLD	3/7/05
39715440007	U061T047	W105'	UPLD	5/16/06
39715600009	U061T048	W75' OF E150'	WTLD	6/25/04
39715720002	U061T049		NDSP	6/24/06
39715720002	U061T049	E75'	WTLD	8/16/06
39715760004	U061T049	W75' of E150'	NDSP	1/8/07
39715800003	U061T050	E105'	WTLD	11/16/01
39715880007	U061T050	W150'	SPUP	2/19/04
39715920006		47th Ave NE	WTLD	11/19/2012
39716240009	U061T079	W150'	WTLD	10/7/05
39716280004	U61T53	W 150'	WTLD	6/28/2013
39716360005	U061T054	E75' OF W150'	NDSP	3/31/03
39716400004	U061T054	E180'	NDSP	10/25/06
39716440006	U061T054	W75'	SPUP	6/4/04
39716600008	U061T056	W180'	UPLD	6/17/01
39716840004	U061T058	W180'	WTLD	12/10/02
39716920005	U061T059	W75' OF E150'	NDSP	1/12/05
39716920005	U061T059	W75' of E150'	SPUP	4/8/05
39717000005	U061T060	S105'	NDSP	9/26/03
39717080009	U061T060	W105'	NDSP	2/12/07
39717160000	U061T061	W75' of E150'	WTLD	7/27/07
39717200009	U061T061	W105'	WTLD	11/16/01
39717200009	U061T061	W105'	WTLD	10/14/05
39717400003	U061T063	E105'	WTLD	9/10/04
39717560008	U061T064	W75' of E180'	UPLD	3/10/05
39717640009	U061T064	E105'	NDSP	12/28/04
39717840003	U061T066	W75'	WTLD	1/18/05
39718000004	U061T067	E180'	NDSP	4/7/06
39718200008	U061T069	W75' OF E150'	UPLD	12/16/03
39718240000	U061T069	E75'	UPLD	4/21/04
39718280002	U061T070	W180'	WTLD	12/21/05
39718400002	U061T071	W75' OF E150'	NDSP	2/20/03
39718480006	U061T071	E75'	UPLD	6/22/06
39718560007	U061T072	W180'	WTLD	10/11/04
39718680000	U061T074	W75'	UPLD	3/12/03
39718800000	U061T075	E75' OF W150'	UPLD	5/2/03
39718920003	U061T075	W75'	WTLD	11/12/03
39719000003	U061T077	E105'	UPLD	7/19/06
39719040005	U061T077	W75' OF E180'	DITCH	9/7/06
39719320000	U061T080	6ACRES	UPLD	11/22/04
39719360002	U061T081	E75'	WTLD	11/29/05
39719680009	U061T083	E75'	WTLD	10/14/04
39719800009	U061T084	W75' of E150'	NDSP	3/22/05
39719920002	U061T085	E75' OF W180'	UPLD	6/7/04
39720000005	U061T085	W75' OF E150'	UPLD	6/7/04
39720040007	U061T085	W105'	MAUP	4/21/05
39720080009	U061T086		SPUP	1/3/06
39720360004	U061T090	W150'	UPLD	4/7/06
39720440005	U061T091	332.11' of E295.26'	DITCH	12/15/05
39731200000	U062T028	W75' OF E180'	WTLD	10/28/03

Folio#	Unit/Tract	Section	Determ	Date
39770040002	U062T001	S180'	UPLD	7/21/03
39770080004	U062T001	N150'	UPLD	8/14/01
39770160102	U062T003	N297'	WTLD	1/26/07
39770320007	U062T005	N1/2	UPLD	10/15/05
39770360009	U062T005	S1/2	WTLD	10/7/04
39770640004	U062T008	N180'	MAUP	10/20/03
39770680006	U062T008	S75'	UPLD	2/9/05
39770760007	U062T009	N150'	WTLD	12/23/03
39770840008	U062T010	N180'	WTLD	2/3/03
39770920009	U062T012	S75'	UPLD	10/3/01
39771000009	U62T12	N180'	WTLD	8/28/2013
39771040001	U062T013	S105'	UPLD	11/27/01
39771120002	U062T013	S75' OF N150'	WTLD	11/2/04
39771160004	U062T013	N75' of S180'	NDSP	5/5/06
39771400007	U062T017	W75' OF E150'	SPUP	10/15/02
39771480001	U062T017	E75'	SPUP	8/15/01
39771520000	U062T018	W75' OF E150'	WTLD	10/14/04
39771640003	U062T018	47th Ave NE	WTLD	3/24/08
39771680005	U062T019	W75' of E150'	SPUP	7/12/07
39771720004	U062T019	E75'	SPUP	5/28/03
39771920008	U062T020	E75 of W180	WTLD	12/18/2014
39772000008	U062T021	E75' OF W180'	NDSP	12/11/03
39772040000	U062T021	W105'	WTLD	10/6/03
39772080002	U062T021	W75' OF E150'	UPLD	5/23/02
39772160003	U062T022	E75' OF W180'	SPUP	3/12/04
39772240004	U062T022	W105'	UPLD	2/17/04
39772320005	U062T023	E75'	NDSP	10/14/04
39772360007	U062T023	W75' OF E150'	UPLD	3/5/04
39772400006	U062T023	W105'	UPLD	7/22/03
39772560001	U062T024	E150'	UPLD	1/18/05
39772600000	U062T025	E75' OF W150'	UPLD	5/23/02
39772640002	U062T025	W75' OF E180'	SPUP	7/13/04
39772760005	U062T026	E105'	NDSP	12/8/05
39772880008	U062T026	E75' OF W150'	UPLD	1/21/02
39773160002	U062T028	E75' OF W150'	WTLD	12/2/04
39773240003	U062T029	W75'	UPLD	6/9/06
39773400005	U062T030	W75' OF E180'	WTLD	4/16/03
39773480009	U062T030	W75'	WTLD	9/21/04
39773520008	U062T030	E105'	WTLD	5/5/06
39773640001	U062T031	E75' OF W150'	NDSP	12/28/04
39773640001	U062T031	E75' of W150'	SPUP	4/19/05
39773680003	U062T031	W75' OF E180'	NDSP	7/19/06
39773680003	U062T031	W75' OF E180'	WTLD	9/12/06
39773720002	U062T032	E75' of W180'	WTLD	9/25/05
39774160001	U062T035	W75' OF E150'	WTLD	3/3/03
39774240002	U062T035	E75' OF W180'	WTLD	10/25/04
39774280004	U062T036	W75' OF E150'	WTLD	10/22/03
39774360005	U062T036	E75'	WTLD	4/15/05
39774400004	U062T036	E75' OF W180'	UPLD	6/22/01
39774440006	U062T037	W150'	WTLD	10/6/03
39774520007	U062T037	E75' OF W180'	UPLD	10/6/03
39774640000	U062T038	E75'	WTLD	6/27/06

Folio#	Unit/Tract	Section	Determ	Date
39774680002	U062T038	W105'	WTLD	2/19/03
39774760003	U062T039	S300'	NDSP	3/13/06
39774880006	U062T040	E75'	SPWE	4/26/04
39774960007	U062T041	E1/2	WTLD	5/16/01
39775040007	U062T043	W75' OF E180'	UPLD	3/5/04
39775120008	U062T043	E105'	UPLD	1/7/08
39775160000	U062T043	W75'	UPLD	5/6/03
39775320002	U062T046	W75' OF E180'	UPLD	3/25/04
39775440005	U062T047	W75'	SPUP	6/25/04
39775840003	U062T049	W105'	UPLD	3/6/02
39775880005	U062T050	W105'	UPLD	7/16/01
39775920004	U062T050	E75'	SPUP	8/3/04
39775960006	U062T050	W75' OF E150'	NDSP	10/28/02
39776000004	U062T050	E75' OF W180'	NDSP	11/22/04
39776000004	U062T050	E75' of W180'	SPUP	3/24/05
39776080008	U062T051	E75'	WTLD	5/28/03
39776120007	U062T051	W180'	UPLD	11/7/02
39776280002	U062T053	W180'	NDSP	11/11/04
39776320001	U062T053	W75' OF E150'	UPLD	7/10/03
39776640008	U062T055	W105'	WTLD	5/16/03
39776680000	U062T055	W75' OF E150'	UPLD	10/20/03
39776720009	U062T056	E75' OF W150'	WTLD	8/5/03
39776720009	U062T056	W75' OF E150'	WTLD	12/2/04
39776800000	U062T056	E75'	NDSP	9/14/04
39776840002	U062T057	W75'	WTLD	8/29/01
39777080007	U062T058	W75' OF E180'	NDSP	10/31/01
39777160008	U062T059	W75'	UPLD	7/26/04
39777400001	U062T060	E75' OF W150'	WTLD	10/12/06
39777520004	U062T062	E180'	WTLD	11/14/02
39777600005	U062T062	E75' OF W150'	WTLD	1/28/03
39777680009	U062T063	W75' OF E180'	WTLD	9/12/06
39777720008	U062T063	W75'	NDSP	9/11/07
39777760000	U062T063	E75' OF W150'	NDSP	7/19/06
39777800009	U062T064	W150'	WTLD	11/11/04
39777880003	U062T064	E105'	UPLD	12/23/02
39777960004	U062T065	W105'	DITCH	10/27/06
39778080006	U062T066	W105'	SPUP	12/2/03
39778160007	U062T66	W75'ofE150'	UPLD	3/28/14- Collier Co
39778360001	U062T068	E75'	UPLD	6/27/06
39778440002	U062T068	E75' OF W180'	SPUP	1/23/03
39778480004	U062T069	W75' OF E150'	SPUP	12/6/01
39778561004	U062T069	W105'	WTLD	3/22/06
39778800008	U062T071	E75'	WTLD	12/13/04
39779040003	U062T150	E75'	WTLD	8/29/07
39779200005	U062T074	E180'	MAUP	1/6/03
39779360000	U062T075	E75' OF W150'	WTLD	6/26/02
39779480003	U062T076	W75' OF E18'	UPLD	9/23/03
39779840009	U062T078	W75'W150'	WTLD	8/22/07
39779880001	U062T079	W75' OF E180'	UPLD	5/16/06
39779920000	U062T079	E75' OF W150'	SPUP	12/22/04
39780000003	U062T079	E105'	NDSP	5/5/04
39780000003	U062T079	E105'	SPUP	4/17/05

Folio#	Unit/Tract	Section	Determ	Date
39780080007	U062T080	W150'	UPLD	10/14/04
39780240009	U062T081	E75' of W180'	UPLD	4/11/06
39780280001	U062T082	W75' OF E150'	UPLD	8/23/02
39780440003	U062T083	W75' of E150'	WTLD	1/26/06
39780480005	U062T083	E75'	WTLD	8/1/01
39780560006	U062T084	W105'	UPLD	4/16/03
39780600005	U062T084	E75' of W180'	WTLD	1/14/05
39780640007	U062T084	E75'	WTLD	2/3/03
39780680009	U062T084	W75' OF E150'	WTLD	12/28/04
39780760000	U062T085	W75' OF E150'	UPLD	6/25/04
39780920002	U062T086	W75' OF E150'	UPLD	2/4/04
39781000002	U062T086	E75' of W180'	MAUP	9/8/05
39781160007	U062T088	E75' OF W180'	WTLD	9/12/06
39781200006	U062T088	W75' OF E150'	WTLD	10/28/03
39781280000	U062T088	E75'	NDSP	12/2/04
39781320009	U062T089	E105'	WTLD	7/7/04
39781360001	U062T089	W75'	UPLD	10/12/01
39781480004	U062T090	E105'	NDSP	11/11/04
39781520003	U062T090	W75' OF E180'	UPLD	3/5/04
39781560005	U062T090	E75' OF W150'	UPLD	6/9/03
39781720007	U062T091	W75'	UPLD	3/6/02
39781760009	U062T091	W75' OF E180'	UPLD	12/9/03
39781840000	U062T092	W75'	SPUP	3/31/04
39781880002	U062T092	E75' OF W150'	MAUP	1/23/03
39781920001	U062T093	W75'	WTLD	1/23/07
39782160006	U062T094	W75' of E180'	WTLD	1/26/06
39782240007	U062T095	E75' of W150'	NDSP	10/11/05
39782320008	U062T095	E150'	WTLD	9/1/06
39782360000	U062T096	W150'	UPLD	9/24/01
39782480003	U062T097	E75' OF W180'	UPLD	11/18/02
39782520002	U062T097	E75'	UPLD	6/7/04
39782600003	U062T098	W105'	SPUP	3/6/02
39782680007	U062T098	W75' OF E150'	SPUP	9/28/04
39782720006	U062T098	E75'	UPLD	4/1/02
39782880001	U062T100	E75'	UPLD	8/1/02
39783000000	U062T100	W105'	WTLD	9/25/05
39783240006	U062T102	W105'	UPLD	6/25/01
39783320007	U062T010	E75' OF W180'	UPLD	10/9/06
39783360009	U062T103	W75' of E150'	UPLD	5/5/06
39783560003	U062T104	E150'	UPLD	7/29/02
39783640004	U064T104	E75'	MAUP	5/16/05
39783760007	U062T105	E105'	UPLD	7/12/01
39783880000	U062T106	W75' OF E150'	UPLD	9/26/03
39783920009	U062T106	E75' OF W150'	MAUP	4/21/03
39783960001	U062T107	E105'	UPLD	3/3/03
39784120002	U062T108	W75'	UPLD	9/4/01
39784160004	U062T108	E75' OF W150'	UPLD	6/11/01
39784200003	U062T108	W75' OF E180'	UPLD	1/12/05
39784240005	U062T108	E105'	UPLD	2/11/05
39784400007	U062T110	W75'	UPLD	12/2/04
39784600001	U062T111	W75' of E180'	NDSP	4/16/07
39784680005	U062T112	E75' OF W150'	UPLD	7/30/03

Folio#	Unit/Tract	Section	Determ	Date
39784720004	U062T112	W75'	UPLD	2/4/05
39784760006	U062T112	E105'	MAUP	10/28/03
39784800005	U062T112	W75' OF E180'	UPLD	12/5/02
39784920008	U062T113	W105'	UPLD	4/21/04
39784960000	U062T113	E75'	UPLD	12/7/04
39785040000	U062T114	E75' W180"	UPLD	8/7/07
39785080002	U062T114	W75' OF E150'	MAUP	11/25/02
39785320005	U062T116	W75' OF E150'	UPLD	11/19/03
39785360007	U062T116	W105'	UPLD	6/29/07
39785400006	U062T116	E75'	UPLD	3/12/04
39785440008	U062T116	E75' OF W180'	UPLD	8/16/01
39785520009	U062T117	E150'	UPLD	1/26/06
39785560001	U062T117	W105'	UPLD	12/14/06
39785600000	U062T118	E150'	UPLD	11/11/04
39785640002	U062T118	E75' OF W180'	UPLD	11/14/02
39785720003	U062T119	W75' of E150'	SPUP	9/21/05
39785840006	U062T119	E75'	UPLD	8/18/03
39785920007	U062T120	E150'	UPLD	6/18/04
39786000007	U062T122		UPLD	9/25/05